



# apple peripherals

## APPLE II

## LANGUAGE CARD



*Reynolds*

---

# LANGUAGE CARD

---

A2B0043

---



**apple peripherals**

©1981 Apple Computer Inc.

 **apple computer inc.**

10260 Bandley Drive  
Cupertino, California 95014  
(408) 996-1010

# PACKING LIST

Apple II

## APPLE LANGUAGE CARD



10260 Bandley Drive  
Cupertino, California 95014  
(408) 996-1010

This package should contain the following items:

Item	Quantity	Part Number	Description
1	1	670-4006	Apple Language Card
2	1	030-0183	Apple Warranty Registration Card
3	1	030-0217	Manual: Apple Language Card Installation and Operation
4	1	918-0017	Chip (Integrated Circuit) Extractor
5	1	030-0136	Apple User Input Form

We regret if anything is missing. To receive any missing items, follow the instructions below:

1. On the above list, circle missing item. 2. Fill in the blanks:

DATE OF PURCHASE			
CUSTOMER'S NAME		DEALER'S NAME	
STREET		STREET	
CITY		CITY	
STATE/COUNTRY		STATE/COUNTRY	
ZIP/POSTAL CODE		ZIP/POSTAL CODE	

3. In the U.S.A., mail this packing list to: **Apple Service Dept.  
10260 Bandley Drive  
Cupertino, CA 95014**


Note: Outside the U.S.A., mail this packing list to the distributor or the Apple Computer office in the country where this product was purchased.

Apple II



# Apple Language Card

Installation and Operation Manual



 **apple computer inc.**

10260 Bandley Drive  
Cupertino, California 95014  
(408) 996-1010

## NOTICE

---

Apple Computer reserves the right to make improvements in the product described in this manual at any time and without notice.

## DISCLAIMER OF ALL WARRANTIES AND LIABILITY

---

APPLE COMPUTER MAKES NO WARRANTIES, EITHER EXPRESS OR IMPLIED, WITH RESPECT TO THIS MANUAL OR WITH RESPECT TO THE SOFTWARE DESCRIBED IN THIS MANUAL, ITS QUALITY, PERFORMANCE, MERCHANTABILITY, OR FITNESS FOR ANY PARTICULAR PURPOSE. APPLE COMPUTER SOFTWARE IS SOLD OR LICENSED "AS IS." THE ENTIRE RISK AS TO ITS QUALITY AND PERFORMANCE IS WITH THE BUYER. SHOULD THE PROGRAMS PROVE DEFECTIVE FOLLOWING THEIR PURCHASE, THE BUYER (AND NOT APPLE COMPUTER, ITS DISTRIBUTOR, OR ITS RETAILER) ASSUMES THE ENTIRE COST OF ALL NECESSARY SERVICING, REPAIR, OR CORRECTION AND ANY INCIDENTAL OR CONSEQUENTIAL DAMAGES. IN NO EVENT WILL APPLE COMPUTER BE LIABLE FOR DIRECT, INDIRECT, INCIDENTAL, OR CONSEQUENTIAL DAMAGES RESULTING FROM ANY DEFECT IN THE SOFTWARE, EVEN IF APPLE COMPUTER HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES. SOME STATES DO NOT ALLOW THE EXCLUSION OR LIMITATION OF IMPLIED WARRANTIES OR LIABILITY FOR INCIDENTAL OR CONSEQUENTIAL DAMAGES, SO THE ABOVE LIMITATION OR EXCLUSION MAY NOT APPLY TO YOU.

This manual is copyrighted. All rights are reserved. This document may not, in whole or part, be copied, photocopied, reproduced, translated or reduced to any electronic medium or machine readable form without prior consent, in writing, from Apple Computer

© 1981 by APPLE COMPUTER  
10260 Bandley Drive  
Cupertino, California 95014  
(408) 996-1010

The word Apple and the Apple Logo are registered trademarks of APPLE COMPUTER

APPLE Product #A2L0043  
(030-0217-B)

---

**WARNING:** This equipment has been certified to comply with the limits for a Class B computing device, pursuant to Subpart J of Part 15 of FCC Rules. Only peripherals (computer input/output devices, terminals, printers, etc.) certified to comply with the Class B limits may be attached to this computer. Operation with non-certified peripherals is likely to result in interference to radio and TV reception.

Apple II

---

# Apple Language Card

---

Installation and Operation Manual

PLEASE READ THIS MANUAL BEFORE ATTEMPTING TO INSTALL THE LANGUAGE CARD IN THE APPLE. INCORRECT INSTALLATION COULD CAUSE PERMANENT DAMAGE TO BOTH THE LANGUAGE CARD AND THE APPLE.



Apple Software Support  
Apple Computer Inc.  
10260 Bandley Drive  
Cupertino, CA 95014

DATE \_\_\_\_\_

CONTROL # \_\_\_\_\_

843496

INTERNAL  
USE ONLY

**Apple Owner**

**Apple Dealer**

Name: \_\_\_\_\_ Person to Contact: \_\_\_\_\_

Company: \_\_\_\_\_ Store Name: \_\_\_\_\_

Address: \_\_\_\_\_ Address: \_\_\_\_\_

City/State/Zip: \_\_\_\_\_ City/State/Zip: \_\_\_\_\_

Home Phone: ( ) \_\_\_\_\_ Phone: ( ) \_\_\_\_\_

Work Phone: ( ) \_\_\_\_\_ Service Center # \_\_\_\_\_

Received

Response  
Sent

This is a  report of a problem with an Apple product.  
 suggestion for changing or improving an Apple product.

Describe your Apple hardware set-up:

Memory Size

Apple II Serial No. \_\_\_\_\_  
(appears on bottom side of Apple)

Apple II Plus

16K  48K

32K  Other \_\_\_\_\_

List any Cards plugged into the slots inside the Apple (e.g., Disk Controller Cards, Language Card) and the accessories (e.g., Disk II Drives) connected to them:

Slot 0* _____	Slot 4 _____
Slot 1 _____	Slot 5 _____
Slot 2 _____	Slot 6 _____
Slot 3 _____	Slot 7 _____

Disposition

\*Note: These are Slot Numbers, not Disk Drive numbers or Pascal Volume Numbers.

Type of Video Display used: \_\_\_\_\_

Any special P/ROMs: \_\_\_\_\_

Game I/O Devices (e.g., game paddles, light pen, joy stick): \_\_\_\_\_

Other: \_\_\_\_\_

Describe any modifications to the Apple hardware: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_


(over)



To mail, simply . . .

1. DETACH mailer
2. REMOVE tape
3. FOLD
4. PRESS where indicated

⇩ DETACH ⇩



**BUSINESS REPLY MAIL**

FIRST CLASS PERMIT #453 CUPERTINO, CA

POSTAGE WILL BE PAID BY:



Attn: Marketing Services  
10260 Bandley Drive  
Cupertino, California 95014

NO POSTAGE  
NECESSARY  
IF MAILED  
IN THE  
UNITED STATES









*Scanned by cvxmelody*

*<http://www.cvxmelody.net/AppleUsersGroupSydneyAppleIIDiskCollection.htm>*